


01/99 AWA 123-1546

A-NZM 14

01/99 AWA 123-1546

Einbau in 3- und 4polige Schalter ohne Ausfahreinheit AF
Mounting in 3/4-pole switches without withdrawable unit AF
Montage dans disjoncteurs tri- et tétrapolaires sans unité de débrogage AF
Montaggio sugli interruttori 3 e 4polari senza unità estraibile AF
Montaje en interruptores automáticos sin unidad seccionable AF
Монтаж в трёх- и четырёхполюсные выключатели без выдвижного блока AF
装入无可抽取单元 AF 的3芯或4芯开关



Lebensgefahr durch elektrischen Strom!

Nur Elektrofachkräfte und elektrotechnisch unterwiesene Personen dürfen die im folgenden beschriebenen Arbeiten ausführen.

Electric current! Danger to life!

Only skilled or instructed persons may carry out the following operations.

Tension électrique dangereuse !

Seuls les personnes qualifiées et averties doivent exécuter les travaux ci-après.

Pericolo di morte causa corrente elettrica!

Solo persone istruite e avvertite possono eseguire le operazioni di seguito riportate.

¡Corriente eléctrica! ¡Peligro de muerte!




El trabajo a continuación descrito debe ser realizado por personas cualificadas y advertidas.

Электрический ток! Опасно для жизни!

Только специалисты или проинструктированные лица могут выполнять следующие операции.

触电危险!

只允许专业人员和受过专业培训的人员进行下列工作。



H 2, H 3



Gerät komplett spannungsfrei schalten

De-energize the device completely



Mettre l'appareil hors tension

Mettere l'apparecchio completamente fuori tensione

El aparato debe estar completamente sin tensión

Прибор полностью отключить от сети.

使设备完全不带电



Die folgenden Arbeitsschritte dürfen nicht bei Überkopfmontage durchgeführt werden.

The following working steps must not be carried out with overhead installation.



Les étapes suivantes ne doivent pas être effectuées en cas de montage au-dessus de la tête.

Le seguenti operazioni dovrebbero essere eseguite in condizioni di lavoro agevolate.

Las siguientes etapas de trabajo no pueden realizarse si el interruptor está instalado como se indica en el dibujo.

Следующие операции не производить при монтаже над головой.

下列工作步骤不允许在过顶安装时执行。




1

6 × M6 × 90



H 3




2


4 × M5 × 45



H 2





3




01/99 AWA 123-1546

1




Montage
Mounting
Montage
Montaggio
Instalación
Монтаж
安裝

**2****3a**

Variante A
Mit roter Auslöse-Lasche
With red trip lever
Avec patte de déclenchement rouge
Con staffa sganciatore rossa
Con barra de disparo roja
Вариант А
С красным рычагом сбрасывания
A 型
带有红色触发板


**3b**

Variante B
Mit schwarzer Auslöse-Lasche
With black trip lever
Avec patte de déclenchement noire
Con staffa sganciatore nera
Con barra de disparo negra
Вариант Б
С чёрным рычагом сбрасывания
B 型
带有黑色触发板

**4a****4b**


01/99 AWA 123-1546

A-NZM 14




A-NZM 14

Mit Zusatzfunktionen M oder LUE
 With additional functions M or LUE
 Avec fonctions supplémentaires M ou LUE
 Con funzioni aggiuntive M o LUE
 Con funciones adicionales M ó LUE
 С дополнительными функциями М или LUE
 帶有附加功能 M 或 LUE





1

Demontage A-NZM 14
Dismounting A-NZM 14
Démontage du A-NZM 14
Smontaggio A-NZM 14
Desmontaje A-NZM 14
Демонтаж прибора A-NZM 14
A-NZM 14 拆卸



2a


Variante A
Mit roter Auslöse-Lasche
With red trip lever
Avec patte de déclenchement rouge
Con staffa sganciatore rossa
Con barra de disparo roja
Вариант А
С красным рычагом сбрасывания
A 型
带有红色触发板



01/99 AWA 123-1546

2b


Variante B
Mit schwarzer Auslöse-Lasche
With black trip lever
Avec patte de déclenchement noire
Con staffa sganciatore nera
Con barra de disparo negra
Вариант Б
С чёрным рычагом сбрасывания
B 型
带有黑色触发板




For Immediate Delivery call KMParts.com at (866) 595-9616

1


A-NZM 14




2



3




4




01/99 AWA 123-1546

1

A-NZM 14




2




3


01/99 AWA 123-1546




4




TEST 1



TEST 2



TEST 3



TEST 4

